

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	53844	((load force weight stress strain) near2 (test\$5 detect\$5 sens\$5 estimat\$5 identif\$6 evaluat\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:40
L2	457	1 and notches.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:41
L3	43	2 and (curv\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:41
L5	3	3 and (strain near2 gauge).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:42
L6	56	2 and (strain near2 gauge).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:42
L7	51	6 and (connect\$5 coupl\$5 attach\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:43
L8	3497	(oppos\$5 negative counter\$7) near3 ((axial trust) near2 (force load power) torque).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:53
L9	648	8 and gear.clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:54
L10	431	9 and shaft.clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:54
L11	176	10 and power.clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:55
L12	7	11 and thrust near3 (bearing support\$5 coupl\$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:57

L13	131	11 and (bearing support\$5 coupl\$5).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:58
L14	58	13 and pinion	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:58
L15	45	14 and transmission	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:59
L16	9	15 and lock\$5.clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/04/06 10:59